# Safety in Handling and Use

#### Introduction

This technical bulletin provides guidelines for the safe handling and use of Teflon™ AF amorphous fluoroplastic resins. Temperatures, ventilation, scrap disposal, soldering, and machining are considered.

## Pyrolysis Studies—Weight Loss vs. Temperature

Teflon" AF resins are thermally stable up to about 360 °C (680 °F) in air. Using sensitive analytical techniques, the isothermal rate of weight loss of Teflon" AF in air at 360 °C (680 °F) has been shown to be 0.2-0.6%/hr. Compared with other polymers, the weight loss rates for Teflon" AF resins are extremely low and similar to rates for Teflon" FEP.

#### **Decomposition Products**

When Teflon" AF resins are decomposed in air at temperatures from 360–450 °C (680–842 °F), products observed are HF from reaction of  ${\rm COF}_2$  with moist air,  ${\rm COF}_2$ , CO, and hexafluoroacetone (HFA). The amount of HFA evolved upon complete decomposition at 500 °C (932 °F) is up to 100–200 mg/g of sample.

The OSHA permissible exposure limit for HF is 3 ppm and for HFA is 0.1 ppm. In animal tests, HFA has been shown to be a potent reproductive and developmental toxin. To protect against reproductive or developmental hazards from HFA fumes, Chemours recommends an exposure limit of 0.1 ppm for men and women not of childbearing capability, and 0.005 ppm for women of childbearing capability. A skin notation, denoting that measures should be taken to protect against significant skin absorption, applies for HFA hydrates.

#### **Handling Practices**

Teflon" AF resins may contain parts per million of residual HFA. Because HFA hydrates are readily absorbed through the skin, it is necessary to avoid skin contact with the resin during processing. Chemours recommends the use of protective gloves if handling of the resin is required during manufacturing operations.

Some residual gases (including HF, COF<sub>2</sub>, CO, and HFA) that diffuse from Teflon™ AF resins, even at room temperature, may be harmful. Therefore, to avoid exposure, all resin containers should

be opened and used only in well-ventilated areas using local exhaust ventilation (LEV).

In addition, it is recommended that exhaust hoods be installed to remove all of the off-gases released from hot polymers in work areas. For this purpose, a number of hood designs are shown in Figure 1. These designs present several alternatives to allow adequate exhaust volumes for effective capture and removal of all off-gases.

The types of situations normally encountered and the capture velocities needed to remove all the gases from the local vicinity of the hot polymer are summarized in Table 1.

The type of work situation is selected from Table 1, and the centerline velocity required to capture all of the gases is then used to calculate the volumetric rate of air flow (in m³s/cfm) required for the hood selected from Figure 1. For example, in the extrusion coating of wire, a capture velocity of 1 m/s (200 fpm) may be needed. A hood of the plain-opening design with an area of its face of 0.05 m² (0.5 ft²) is placed 0.15 m (0.5 ft) above the discharge face of the extruder. To remove all the gases generated at the face of this hood, an air volume of 600 cfm (0.28 m³/s) is needed, as calculated below (note that all dimensions must be expressed in meters or feet):

 $Q = V (10X^2 + A)$ 

 $Q = 200 (10 [0.5]^2 + 0.5)$ 

Q = 600 cfm

 $O = V (10X^2 + A)$ 

 $Q = 1 (10 [0.15]^2 + 0.05)$ 

 $Q = 0.28 \,\text{m}^3/\text{s}$ 

The importance of locating the hood opening close to the hot polymer is indicated by the fact that the "X" dimension is raised to the second power in the above equation. Thus, if this dimension were doubled in the above example, the volumetric rate of air flow required would increase to 200 ( $10 \times 1^2 + 0.5$ ) = 2100 cfm/1.0 m³/s, a rise of 250%.

#### Machining

In grinding, sawing, and machining of Teflon® AF, measures should be taken to ensure that temperatures are maintained below 360 °C (680 °F). Generally, coolants are recommended in machining fluoroplastic resins to improve production rates and quality, and they can serve to control any tendency toward overheating.



### Respirable Dust

In any manufacturing or handling operation where dust from Teflon® AF may be created, the concentration of airborne dust should not be permitted to exceed the OSHA permissible exposure limits of 5 mg/m³ respirable dust or 15 mg/m³ total dust.

It is strongly recommended that tobacco not be used or carried in open packs around machining operations or where resin dust may be encountered, because smoking tobacco contaminated with fluoroplastic dust will result in inhalation of toxic thermal decomposition products.

### Soldering and Melt Stripping

The combined effects of temperature, quantity of resin, exposure time, and ventilation conditions during soldering and melt stripping are unlikely to produce conditions of toxicological significance. Any special practices that may be warranted will follow the rules applicable to any soldering work. For example, prolonged soldering in confined spaces where natural air circulation is restricted will require mechanical ventilation. The same is true for shop areas where a number of workers are engaged in soldering or melt stripping operations. Normal ventilation provided for worker comfort usually provides adequate safety for these operations. As an added measure during melt stripping and soldering, many shops use an exhaust duct at each work station.

### **Scrap Disposal**

Disposal of scrap Teflon AF presents no special problem to the user. It is best to dispose of such scrap in a landfill dump without burning.

Small amounts of scrap, up to approximately 5 kg (10 lb) at a time, are often incinerated along with general plant refuse. The incinerator should have sufficient draft to exhaust all combustion products to the stack. Normal care should be taken to avoid breathing smoke and fumes from any fire. In addition, because many polymers produce acids in their combustion products (in the presence of moisture, decomposition products of fluoroplastics contain HF), the stack should be high enough to dilute the acid content of the exhaust gases to an acceptable level. HF causes strong eye and nose irritation before approaching systemically toxic levels. It is also capable of etching glass. In addition, vegetation is particularly sensitive to HF. Where desirable vegetation is present, do not burn scrap fluoroplastics in an open dump during periods of heavy humidity, fog, or smog.

In the reclamation of metals by melting of scrap, it is advisable first to remove any nonmetallic components in order to avoid generating more organic vapors than necessary. The furnace should have sufficient draft to exhaust all gases to the stack.

Figure 1. Hood Design Data

Hood Types	Description	Aspect Ratio, H/W	Air Rate**
XWH	Slot	0.2 or less	Q = 3.7 WVX
X	Flanged slot*	0.2 or less	Q = 2.8 WVX
H	Plain opening	0.2 or greater and round	Q = V (10X <sup>2</sup> + A)
×	Flanged opening*	0.2 or greater and round	$Q = 0.75V (10X^2 + A)$
H	Booth	To suit work	Q = VA = VWH
	Canopy	To suit work	Q = 1.4 PDV

<sup>\*</sup>Wherever possible, flanges should be provided to eliminate air flow from ineffective zones where no contaminant exists. Increasing the hood effectiveness in this manner will usually reduce air requirements by 25%. For most applications, the flange width can be equal to the hood diameter or side; but, need not exceed 15 cm (6 in).

V = Centerline velocity at X distance from face of hood, m/s (fpm) (use recommended capture velocities from Table 1)

X = Distance from source to face of hood, m (ft)

Q = Air volume, m<sup>3</sup>/s (cfm)

A = Area at face of hood, m<sup>2</sup> (sq ft)

P = Perimeter of work, lin m (lin ft)

D = Height above the work, m (ft)

H = Height of hood, m (ft)

W = Width of hood, m (ft)

<sup>\*\*</sup>Nomenclature

Small hood—local control only

Table 1. Capture Velocities Recommended in Various Work Situations

Dispersion of Contaminants into Air	Examples	Capture Velocity, m/s (fpm)		
Released with practically no velocity into quiet air	Drying of fluoroplastic resins— granular, powder, cubes; evaporation of solvents, water, etc.	(0.25-0.50) 50-100		
Released at low velocity into moderately still air	Spray coating with solutions. Normal blending of fluoroplastic cubes or powders. Molding of fluoroplastic resins	(0.50-1.0) 100-200		
Active generation into zone of rapid air motion	Melt extrusion of fluoroplastic resins. Injection and transfer molding of resins	(1.0–2.5) 200–500		
Released at high initial velocity into zone of very rapid air motion	Grinding and machining of parts from fluoroplastic resins. High- speed mixing of fluoroplastic powders in turbulent mode	(2.5–10.0) 500–2,000		
In each category above, a range of capture velocities is shown. The proper choice of values depends on several factors:				
Lower End of Range  Room air current minimal or favorable to capture  Contaminants of low toxicity  Intermittent, low production		<ul> <li>Upper End of Range</li> <li>Disturbing room air currents</li> <li>Contaminants of high toxicity</li> <li>High production, heavy use</li> </ul>		

#### HOW TO USE THE TEFLON" BRAND NAME WITH YOUR PRODUCT

Large hood—large air mass in motion

Teflon" is a registered trademark of Chemours for its brand of fluoroplastic resins, coatings, films, and dispersions. The Teflon" brand name is licensed by Chemours in association with approved applications. Without a trademark license, customers may not identify their product with the Teflon" brand name, as Chemours does not sell such offerings with the Teflon" trademark. Unlicensed customers may refer to the Chemours product offering with only the Chemours name and product code number descriptor as Chemours sells its product offerings. There are no fair use rights or exhaustion of rights to use the Teflon" trademark from buying from Chemours, a Chemours customer, or a distributor without a trademark license from Chemours.

If you are interested in applying for a trademark licensing agreement for the Teflon™ brand, please visit www.teflon.com/license

CAUTION: Do not use Chemours materials in medical applications involving permanent implantation in the human body or contact with bodily fluids or tissues, unless the material has been provided from Chemours under a written contract that is consistent with Chemours policy regarding medical applications and expressly acknowledges the contemplated use. For further information, please contact your Chemours representative. For medical emergencies, spills, or other critical situations, call (866) 595-1473 within the United States. For those outside of the United States, call (302) 773-2000.

The information set forth herein is furnished free of charge and based on technical data that Chemours believes to be reliable. It is intended for use by persons having technical skill, at their own discretion and risk. The handling precaution information contained herein is given with the understanding that those using it will satisfy themselves that their particular conditions of use present no health or safety hazards. Because conditions of product use are outside our control, Chemours makes no warranties, express or implied, and assumes no liability in connection with any use of this information. As with any material, evaluation of any compound under end-use conditions prior to specification is essential. Nothing herein is to be taken as a license to operate under or a recommendation to infringe any patents.

NO PART OF THIS MATERIAL MAY BE REPRODUCED, STORED IN A RETRIEVAL SYSTEM OR TRANSMITTED IN ANY FORM OR BY ANY MEANS ELECTRONIC, MECHANICAL, PHOTOCOPYING, RECORDING OR OTHERWISE WITHOUT THE PRIOR WRITTEN PERMISSION OF CHEMOURS.

# For more information, visit teflon.com/industrial

### For sales and technical support contacts, visit teflon.com/industrialglobalsupport

© 2016 The Chemours Company FC, LLC. Teflon and any associated logos are trademarks or copyrights of The Chemours Company FC, LLC. Chemours and the Chemours Logo are trademarks of The Chemours Company.